# Web Break Detection

Available on machine models: SP1 & SP1DL

Triggers the mainframe nip to clamp and hold the web in the event of web break due to an improperly prepared splice

Advantages, Functions & Features

- HMI includes step-by-step recovery instructions, reducing recovery time
- Photo electric sensor monitors the presence of web leaving the splice head

Functional Requirements

- Web must be detectable by fiber-optic retro-reflective sensor

Installation Requirements

- Factory option or field installed